

# CORNER RECORD


# COUNTY OF PLACER, CALIFORNIA

City of Unincorporated

Document Number 20150029

Brief Legal Description Lot 6, Lake Manor Subdivision, Book I Maps, Page 2

PLS Job No. 846



S. 2

T. 13 N

R. 8 E

### CORNER TYPE

- Government Corner     Control  
 Meander                     Property  
 Rancho                          Other  
 Date of Survey                    3/13/15

### COORDINATES

(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner ---

- Left as found     Found and tagged     Established     Reestablished     Rebuilt

**Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:**  
Reset the northeast corner of Lot 6 using record information from found 1/2" rebar, commonly accepted as original subdivision corners. Having done other surveys in this same subdivision, the same stature monuments - 1/2" rebar with no tag, have been discovered on each survey. The old 3/4" iron pipe found at the southeast corner of Lot 6, while different in stature, fits record position by holding the found original monuments.

**A description of the physical condition of the monument as found and as set or reset:**

The northeast corner of Lot 6 was searched for and not found. A 5/8" rebar with plastic cap was set in it's place.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction

in conformance with the Professional Land Surveyors' Act

on July 08 20 15

Signed Richard A. Marino

L.S. or R.C.E. Number 6376



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 20 \_\_\_\_\_

and examined and filed August 12, 2015 20 \_\_\_\_\_

Signed Leslie Amberry Title County Surveyor

L.S. or R.C.E. Number 6584



County Surveyor's Comment \_\_\_\_\_

BOOK 18 CORNER RECORDS PAGE 20

● FOUND AS NOTED  
BELIEVED TO BE ORIGINAL

○ NOTHING FOUND OR SET

○ SET 5/8" REBAR; LS6376

ALL DATA PER BOOK 1  
MAPS PAGE 2

