


CORNER RECORD

Document Number _____

City of _____ County of Placer, California

Brief Legal Description Lots 18 & 19, Blk. 4, 102 Park Sub. No. 1, D-51A



CORNER TYPE

S.7 Government Corner Control
TIAN Meander Property
RITE Rancho Other
M.D.M. Date of Survey 6/20/01

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: See pg. 2

A description of the physical condition of the monument as found and as set or reset: See pg. 2


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 6/20/2001.
 Signed Ronald W. Turner P.L.S or R.C.E. No. 4029



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December 31, 2001
 and examined and filed March 13, 2002
 Signed John H. Rietsjens P.L.S or R.C.E. No. 4323
 Title County Surveyor



County Surveyor's Comment _____

BOOK 7 CORNER RECORDS PAGE 38

APN's 98-168-09 & 10

01143

- ... Find 3/4" IP plug LS 5549
- ... Set 3/4" IP plug PLS 4029
- ✕ ... Set nail & tag on conc.

